

Walkthrough Inspection Checklist

Name:	Mill Road School IAQ Team		
School:	295 Mill Road, North Haven	, CT 06473	
Room or	Area: ALL	Date Completed:	11-25-2024
Signature	Todd A. Solli		

Instructions

- 1. Read the *IAQ*Backgrounder and the Background Information for this checklist.
- 2. Keep the
 Background
 Information and
 make a copy of
 the checklist for
 future reference.
- 3. Complete the Checklist.
 - Check the "yes,"
 "no," or
 "not applicable"
 box beside each
 item. (A "no"
 response
 requires further
 attention.)
 - Make comments in the "Notes" section as necessary.
- 4. Return the checklist portion of this document to the IAQ Coordinator.

1.	GROUND LEVEL	Yes	No	N/A
1a.	Ensured that ventilation units operate properly		×	
	Ensured there are no obstructions blocking air intakes			
	Checked for nests and droppings near outdoor air intakes			
	Determined that dumpsters are located away from doors, windows, and outdoor air intakes			
1e.	Checked potential sources of air contaminants near the building	/ 		_
10.	(chimneys, stacks, industrial plants, exhaust from nearby buildings)	X		
1f.	Ensured that vehicles avoid idling near outdoor air intakes			
1g.	Minimized pesticide application			X
_	Ensured that there is proper drainage away from the building (including roof downspouts)			
1i.	Ensured that sprinklers spray away from the building and outdoor			
	air intakes	X		
1j.	Ensured that walk-off mats are used at exterior entrances and that			
	they are cleaned regularly	X		
2.	ROOF			
Wh	ile on the roof, consider inspecting the HVAC units (use the Ventilation Ch	ecklist).	
	Ensured that the roof is in good condition			
2b.	Checked for evidence of water ponding	🛚		
2c.	Checked that ventilation units operate properly (air flows in)	🔽		
2d.	Ensured that exhaust fans operate properly (air flows out)	🔽		
2e.	Ensured that air intakes remain open, even at minimum setting	🔀		
	Checked for nests and droppings near outdoor air intakes	🙀		
2g.	Ensured that air from plumbing stacks and exhaust outlets flows away			
	from outdoor air intakes	🛚		
3.	ATTIC			
3a.	Checked for evidence of roof and plumbing leaks	🗖		X
	Checked for birds and animal nests			X
4.	GENERAL CONSIDERATIONS			
4 0	Ensured that temperature and humidity are maintained within			
₹а.	acceptable ranges	🗅	X	
4h.	Ensured that no obstructions exist in supply and exhaust vents			_
	Checked for odors			_
	Checked for signs of mold and mildew growth			

4.	GENERAL CONSIDERATIONS (continued)	es	No	N/A
4e.	Checked for signs of water damage			
4f.				
4g.	Noted and reviewed all concerns from school occupants	X		
5.	BATHROOMS AND GENERAL PLUMBING			
	Ensured that bathrooms and restrooms have operating exhaust fans	X		
	Water is poured down floor drains once per week (approx. 1 quart of water)	X		
	Water is poured into sinks at least once per week (about 2 cups of water) [X		
	Toilets are flushed at least once per week	X		
6.	MAINTENANCE SUPPLIES			
6a.	Ensured that chemicals are used only with adequate ventilation and when building is unoccupied	_		X
6b.	Ensured that vents in chemical and trash storage areas are operating	_	_	-
	properly	X		
6c.	Ensured that portable fuel containers are properly closed			X
6d.	Ensured that power equipment, like snowblowers and lawn mowers, have			
	been serviced and maintained according to manufacturers' guidelines	X		
7.	COMBUSTION APPLIANCES			
7a.	Checked for combustion gas and fuel odors	X)		
7b.	Ensured that combustion appliances have flues or exhaust hoods	X		
7c.	Checked for leaks, disconnections, and deterioration	X		
7d.	Ensured there is no soot on inside or outside of flue components	K		
8.	OTHER			
8a.	Checked for peeling and flaking paint (if the building was built before			
	1980, this could be a lead hazard)	X		
8b.	Determined date of last radon test	X		
	Last radon was done April 25, 2018. One will be scheduled for this	yea	ar.	

Unsure if vents are working

Vents need to be cleaned of debris

Gutters need to be cleaned of debris

Seven locations around the building have leaking gutter seams

Trash and expired milk need to be discarded properly on back side of building

Missing cover/vent on upper vents X 2

dented under-roof needs repair on south side of building

Interior:

Ceiling tiles either missing or stained and need to be replaced:

502, 500 closet, 308, 207, hallway by 206, 202, 421, Family Resource, 408, 100 hallway, girl's bathroom, main hallway

Boiler room cracked boiler leaking and trash on floor

112 room temperature is over 80 degrees F

310 room temperature is below 65 degrees F

Kiln in art room ceiling tiles need to be repair by Kline vent

312 room has cracked wall block with air seeping in/out of crack

dust in all data rooms needs to be cleaned

light lens in all areas that have dead bugs need to be cleaned

air vents in all areas need to be vacuumed monthly

walk off matts need to be located at all egress locations

Maintain a 3-foot clearance around all electrical panels

2 of 2