

Instructions

- 1. Read the *IAQ Backgrounder* and the Background Information for this checklist.
- 2. Keep the Background Information and make a copy of the checklist for future reference.
- 3. Complete the Checklist.
 - Check the "yes," "no," or "not applicable" box beside each item. (A "no" response requires further attention.)
 - Make comments in the "Notes" section as necessary.
- 4. Return the checklist portion of this document to the IAQ Coordinator.

Walkthrough Inspection Checklist

Name:	Staff Development Area IAQ	Team	
School:	205 Skiff Street, Hamden, C	CT 06517	
Room or .	Area: ALL	Date Completed:	12-20-2024
Signature	Todd A. Solli		

Yes No N/A

1. GROUND LEVEL

		-		,
1a.	Ensured that ventilation units operate properly	X		
1b.	Ensured there are no obstructions blocking air intakes	Q		
1c.	Checked for nests and droppings near outdoor air intakes	Ç		
1d.	Determined that dumpsters are located away from doors, windows, and outdoor air intakes	X		
1e.	Checked potential sources of air contaminants near the building			
	(chimneys, stacks, industrial plants, exhaust from nearby buildings)	ב		X
1f.	Ensured that vehicles avoid idling near outdoor air intakes	X		
1g.	Minimized pesticide application	ב		X
1h.	Ensured that there is proper drainage away from the building (including roof downspouts)	ב	X	
1i.	Ensured that sprinklers spray away from the building and outdoor			
	air intakes	ב		X
1j.	Ensured that walk-off mats are used at exterior entrances and that they are cleaned regularly	X		

2. ROOF

While on the roof, consider inspecting the HVAC units (use the Ventilation Checklist).

2a.	Ensured that the roof is in good condition \Box	X
2b.	Checked for evidence of water ponding \Box	X
2c.	Checked that ventilation units operate properly (air flows in) \Box	X
2d.	Ensured that exhaust fans operate properly (air flows out)	X
2e.	Ensured that air intakes remain open, even at minimum setting \Box	
2f.	Checked for nests and droppings near outdoor air intakes \Box	X
2g.	Ensured that air from plumbing stacks and exhaust outlets flows away	
	from outdoor air intakes	X

3. ATTIC

3a.	Checked for evidence of roof and plumbing leaks \Box	X
3b.	Checked for birds and animal nests	X

4. GENERAL CONSIDERATIONS

4a.	Ensured that temperature and humidity are maintained within	
	acceptable ranges	
4b.	Ensured that no obstructions exist in supply and exhaust vents	
4c.	Checked for odors	
4d.	Checked for signs of mold and mildew growth	

4. GENERAL CONSIDERATIONS (continued)

4e.	Checked for signs of water damage	🛛	
4f.	Checked for evidence of pests and obvious food sources	🔀	
4g.	Noted and reviewed all concerns from school occupants	🙀	

5. BATHROOMS AND GENERAL PLUMBING

5a.	Ensured that bathrooms and restrooms have operating exhaust fans \dots	X	
5b.	Ensured proper drain trap maintenance:		
	Water is poured down floor drains once per week (approx. 1 quart of water) \Box		X
	Water is poured into sinks at least once per week (about 2 cups of water) 🛛		
	Toilets are flushed at least once per week		

6. MAINTENANCE SUPPLIES

6a.	Ensured that chemicals are used only with adequate ventilation and when building is unoccupied	
6b.	Ensured that vents in chemical and trash storage areas are operating	
	properly	
6c.	Ensured that portable fuel containers are properly closed	X
6d.	Ensured that power equipment, like snowblowers and lawn mowers, have	
	been serviced and maintained according to manufacturers' guidelines \Box	X

7. COMBUSTION APPLIANCES

7a.	Checked for combustion gas and fuel odors \Box	X
7b.	Ensured that combustion appliances have flues or exhaust hoods \Box	X
7c.	Checked for leaks, disconnections, and deterioration \Box	X
7d.	Ensured there is no soot on inside or outside of flue components	X

8. OTHER

8a.	Checked for peeling and flaking paint (if the building was built before		
	1980, this could be a lead hazard)		
8b.	Determined date of last radon test		
	Last radon was done Feb. 23, 2018. One will be scheduled for	this	vear

NOTES Exterior:

Only one drain in the back of the building. In addition to this the lower level of the building is built below street level.

East side of building midway

Interior:

While temperatures are input at normal ranges the operation of the HVAC does not always adhere to those temps.

Pest have been observed and management of them have been conducted. Continued monitoring.


Ceiling tiles are stained: Lower level custodial closet next to elevator

Performance Cleaning company has MSDS sheets posted in their custodial closets

Missing exhaust fan in the lower level women's restroom

Vents should be dusted mouthily by Performance

By front foyer vents should be cleaned filters changed First floor Kitchen ceiling tiles near vent should be changed as they are black Second floor copy room vent ceiling tiles need to be replaced and there are stained ceiling tiles Marketing office has ceiling tiles that need to be replaced near vent Flies are in the light lens throughout the building needs to be cleaned



Yes No N/A